Page 1 of 4 June 2011

# FIELD INVESTIGATION SUMMARY REPORT MAY AND JUNE 2011 REMEDIAL INVESTIGATION / FEASIBILITY STUDY (RI/FS) OVERSIGHT R&H OIL / TROPICANA ENERGY SUPERFUND SITE, SAN ANTONIO, TEXAS

This Field Investigation Summary Report summarizes activities at the R&H Oil / Tropicana Energy Superfund Site (the Site) between 23 May and 7 June 2011. It includes an introduction followed by discussions of health and safety issues, weather conditions, and site activities, and a list of references.

## INTRODUCTION

Under the direction of the U.S. Environmental Protection Agency (EPA), EA Engineering, Science, and Technology, Inc. (EA) oversaw ground water investigatory activities conducted by the Potentially Responsible Parties' consultant, Pastor, Behling, and Wheeler (PBW), at the Site.

## Participants included:

- Mr. Chris Villarreal, EPA Task Order Manager
- Mr. Ted Telisak, EA Project Manager
- Ms. Teri McMillan, EA Geologist, Site Manager/Site Health and Safety Officer
- Mr. Duane Thomas, EA Geologist, Site Manager/Site Health and Safety Officer

EA performed field activities in accordance with the following EPA-approved plans:

- RI/FS Oversight Work Plan (EA 2011a)
- Health and Safety Plan (EA 2011b)

This Field Activity Report reports on the following field activities:

- drilling of monitoring wells;
- water sampling from on-site wells.

#### **HEALTH AND SAFETY**

EA was excluded from the daily tailgate safety briefings involving other field crews working at the site. EA conducted its own daily health and safety review at the beginning of each work day.

#### WEATHER CONDITIONS

On 23 through 25 May and 6 and 7 June, high temperatures ranged from 91 to 101 degrees Fahrenheit. Low temperatures ranged from 73 to 77 degrees Fahrenheit. The skies were mostly clear to partly cloudy and there was no precipitation. Winds were generally southerly,

Page 2 of 4 June 2011

sometimes at speeds of 15 to 20 miles per hour (mph) with gusts around 25 mph and other times at speeds of about 10 mph with gusts to about 17 mph.

#### SITE ACTIVITIES

The following paragraphs summarize events noted in the field. More details may be found in the daily field reports in Attachment 1, and in the field logs in Attachment 2. Photographs taken at the site may be found in Attachment 3.

## Well Drilling and Soil Boring

From 23 May through 25 May 2011, EA witnessed the PBW's soil boring and well installation activities. PBW advanced and lithologically-logged direct-push soil borings. In all but one instance, these borings were advanced to a depth of approximately 25 below ground surface (bgs), with the exception of one of the borings (NMW-2) which was advanced to 30 feet bgs. They eventually plugged each hole by filling it with bentonite and then hydrating the bentonite with potable water. At regular depth intervals at each location, they checked for volatile organic compounds (VOCs) with a photoionization detector. Soil samples were collected from three depth ranges and were sent to the PRP's laboratory to be analyzed for total petroleum hydrocarbons (TPH), VOCs, semi-volatile organic carbons (SVOCs), and the 8 Resource Conservation and Recovery Act (RCRA) metals. At two locations, surface soil samples were collected for geotechnical analysis. Two sets of vapor intrusion samples were also collected. In all of the borings witnessed by EA, with the exception of MW-12, there was evidence of hydrocarbon staining, odor, sheen and/or non-aqueous phase liquids (NAPL) present. EA personnel defined hydrocarbon staining as brown oil staining present on the outside of the core sample and defined NAPL as a liquid sheen of oil present within the pore space of the core.

Geoprobe boring advancement witnessed by EA included the following:

MW-12	MW-17	NMW-3
MW-13	MW-18	NMW-4
MW-14	MW-19	NMW-5
MW-15	NMW-1	
MW-16	NMW-2	

These locations are identified in the PRP Field Sampling Plan (PBW 2010). A figure from that plan may be found in Attachment 4, showing locations of the monitoring wells.

EA also witnessed installation of monitoring wells MW-12, MW-14, and MW-18. These wells were installed using a hollow stem auger drill rig.

Additional well installation was planned for later in the week, after EA left the Site. The PBW planned to develop the new wells the following week and then sample them.

Page 3 of 4 June 2011

## **Well Sampling**

On 6 June and 7 June 2011, EA witnessed the PBW's ground water sampling event. PBW sampled MW-5 and NMW-3 for NAPL. MW-6 was not sampled for NAPL, due to the inability to collect the necessary volume. NAPL samples were sent to an off-site laboratory for analysis of TPH, VOC, and physical properties.

PBW also sampled ground water from the following wells:

MW-1	MW-5	MW-14
MW-2	MW-6	MW-15
MW-3	MW-12	
MW-4	MW-13	

PBW also measured physical parameters and collected samples for laboratory analysis. Ground water samples were sent off-site for analysis of VOCs, SVOCs, RCRA 8 metals, and TPH.

## **Plan Derivations**

The following are a summary of Field Sampling Plan (PBW 2010) derivations noted by EA personnel during oversight of PBW. Additional information can be found in the Daily Field Reports and Field Logbook (Attachments 1 and 2, respectively).

- Soil samples were taken from 0.5 feet to 4 feet bgs, whereas the Field Sampling Plan states that samples will be taken at a maximum of 1 foot intervals.
- It was noted that the decontamination procedures for inside the geoprobe core barrel were not thorough prior to starting borehole MW-17. It is noted this issue was resolved following comment be EA personnel.
- Completion of monitoring well MW-12 was not completed with the minimum 2 foot sand pack above the filter pack. Completion of MW-14 and MW-18 were completed to specifications.

### REFERENCES

EA Engineering Science and Technology, Inc. (EA). 2011a. Remedial Investigation / Feasibility Study Oversight Work Plan. R&H Oil / Tropicana Energy Superfund Site. San Antonio, Bexar County, Texas. April.

EA. 2011b. Health and Safety Plan. R&H Oil / Tropicana Energy Superfund Site. San Antonio, Bexar County, Texas. May.

Page 4 of 4 June 2011

Pastor, Behling, & Wheeler. 2010. Field Sampling Plan. R&H Oil / Tropicana Energy Superfund Site. San Antonio, Bexar County, Texas. September.

EA Project No.: 14342.74 June 2011

## ATTACHMENT 1 DAILY FIELD REPORTS

DAILY FIELD ACTIVITIES SUMMARY REPORT			
PROJECT NAME: R&H Oil/Tropicana Energy Site, San Antonio, Texas			
Date: 05/23/11	Shift Beginning: 13:30 hours		Shift Ending: 17:30 hours
RAC II Contract No	Contract No.: EP-W-06-004		Task Order No.: 0074
EPA Region 6 TOM: Chris Villarreal		Project Manager: Ted Telisak	
Design Manager: N/A		Site Geologist: Teri McMillan	
Design Engineer: N/A		Site Engineer: N/A	
Personnel on site	Name	Affiliation	Reason for being on site
EA:	Teri McMillan	EA	Drilling Oversight
Subcontractors:		Vortex	Driller
Other:	Chris Villarreal	EPA	Drilling Oversight
	Chris Moore	PBW	Environmental Consultant
Ouici.	Tim Nickels	PBW	Environmental Consultant
	Roberta McClure	PBW	Environmental Consultant

#### **Work Performed**

Pastor, Behling & Wheeler, LLC (PBW) is the environmental consultant that is conducting the remedial investigation field activities. EA is providing oversight of field activities on behalf of EPA.

Upon our arrival at the site, PBW informed EPA and EA that one monitoring well was installed using a Geoprobe® outfitted with hollow stem augers. Installing the monitoring well using the Geoprobe® was not efficient; therefore, PBW decided it would be more efficient to only advance soil boring at all well locations to lithologically log and collect soil samples for laboratory analysis. A larger drilling rig is scheduled to arrive at the site tomorrow to install the monitoring wells adjacent to the soil borings that were previously advanced.

EA oversaw the advancement of four borings (MW-18, MW-14, MW-12 and NMW-1) using a Geoprobe®. All four soil borings were advanced to a total depth of 25 feet bgs. Soil samples were collected in 5 foot long acetate sleeves. PBW logged, collected headspace measurements with a PID every 2 feet, and collected three soil samples from each boring at the following intervals:

- 0-0.5 feet bgs collected by first clearing the upper 1 to 2 inches of top soil and then samples collected.
- 0.5-5 feet bgs collected a soil sample from this interval based on olfactory and visual observations. It was mentioned to EPA and PBW that the work plan specified that this interval should be from 0.5 to 4 feet bgs. PBW corrected their procedure after NMW-1.
- 5- 25 feet bgs vadose zone based on highest headspace measurement obtained by using a PID.

Soil samples were to be submitted for analysis of TPH, VOCs (Terra Core Method), SVOCs and RCRA 8 Metals.

Borehole MW-18 was backfilled with bentonite and hydrated. The remaining boreholes MW-14, MW-12, and NMW-1 were left open and borehole temporarily covered. The water level was to be measured in well MW-14 prior to PBW leaving the site. Due to the tight nature of the soils beneath the site the saturated zone is difficult to discern in the soil samples. The water level was measured in well MW-1 and was approximately 17 feet bgs. PBW stated that the water level had previously been at approximately 14 feet bgs.

The location of MW-12 was adjusted in the field due to the presence of bees in the area. In addition, at boring MW-12 the upper two feet of soil was collected for geotechnical analysis, as well as collecting a 1-

## DAILY FIELD ACTIVITIES SUMMARY REPORT

2' sample in an acetate sleeve to be analyzed for a vapor transport package.

Boring NMW-1 had visible oil staining present from approximately 10 feet to 25 feet. PBW indicated that minor staining (oil sheen) was present in the other three borings.

## **Anticipated Activities for the Following Day**

Continue oversight of Geoprobe® and monitoring well installation activities.

## Report prepared by (name and date)

Teri McMillan 5/23/11

DAILY FIELD ACTIVITIES SUMMARY REPORT				
PROJECT NAME: R&H Oil/Tropicana Energy Site, San Antonio, Texas				
Date: 05/24/11	Shift Beginning: 8:15 ho	urs	Shift Ending: 18:35 hours	
RAC II Contract No	o.: EP-W-06-004		Task Order No.: 0074	
EPA Region 6 TOM: Chris Villarreal		Project Manager: Ted Telisak		
Design Manager: N/A			Site Geologist: Teri McMillan	
Design Engineer: N	N/A		Site Engineer: N/A	
Personnel on site	Name	Affiliation	Reason for being on site	
EA:	Teri McMillan	EA	Drilling Oversight	
Subcontractors:	Robert Joiner Cody Clayton Derek Withoff	Vortex	Driller	
Other:	Chris Villarreal Marilyn Long Dani Sattman Eric Pastor Chris Moore Tim Nickels Roberta McClure	EPA TCEQ TCEQ PBW PBW PBW	Drilling Oversight Drilling Oversight Drilling Oversight Environmental Consultant Environmental Consultant Environmental Consultant Environmental Consultant Environmental Consultant	

#### **Work Performed**

Pastor, Behling & Wheeler, LLC (PBW) is the environmental consultant that is conducting the remedial investigation field activities. EA is providing oversight of field activities on behalf of EPA.

EA oversaw the advancement of nine borings (MW-16, MW-13, NMW-2, MW-15, NMW-3, MW-17, MW-19, NMW-5 and NMW-4) using a Geoprobe®. All nine soil borings, except for boring NMW-2, were advanced to a total depth of 25 feet bgs. NMW-2 was advanced to 30 feet bgs. Soil samples were collected in 5 foot long acetate sleeves. PBW logged continuously, collected headspace measurements with a PID every 2 feet, and collected three soil samples from each boring at the following intervals:

- 0-0.5 feet bgs collected by first clearing the upper 1 to 2 inches of top soil and then samples collected.
- 0.5-4 feet bgs collected a soil sample from this interval based on olfactory and visual observations.
- 5- 25 feet bgs vadose zone soil sample based on highest headspace measurement obtained by using a PID. It was noted that many samples were collected from this interval within the saturated zone. PBW decided to collect the sample with the highest headspace measurement from the 5-25 foot interval regardless of it being in the vadose or saturated zone.

Soil samples were to be submitted for analysis of TPH, VOCs (Terra Core Method), SVOCs and RCRA 8 Metals. Boreholes were plugged using bentonite hole plug hydrated.

A water level was not measured in borehole MW-14 prior to PBW leaving the site on 23 May 2011. Instead a water level was measured in borehole MW-14 on 24 May 2011, and it was approximately 22 feet bgs.

Evidence of hydrocarbon odor was noted in all borings advanced today. Many borings had hydrocarbon staining present. Boring MW-13 located on the northern portion of the site, had significant contamination present, with the upper 7 feet of soil saturated with black wet product. In addition, PBW field staff indicated that NAPL was present when gauging borehole MW-17.

At MW-15 a boring was advanced to 5 feet to obtain a soil sample within the acetate liner from 1 to 2 feet

## DAILY FIELD ACTIVITIES SUMMARY REPORT

for analysis of the vapor intrusion package. A 2 foot split spoon with brass sleeves inside was pushed adjacent to well MW-20 (well was installed on 23 May 2011) for additional geotechnical analysis.

## **Anticipated Activities for the Following Day**

Oversight of monitoring well installation activities.

## **Report prepared by (name and date)**

Teri McMillan 5/24/11

DAILY FIELD ACTIVITIES SUMMARY REPORT			
PROJECT NAME: R&H Oil/Tropicana Energy Site, San Antonio, Texas			
Date: 05/25/11	Shift Beginning: 8:00 ho	urs	Shift Ending: 16:20 hours
RAC II Contract No.: EP-W-06-004		Task Order No.: 0074	
EPA Region 6 TOM: Chris Villarreal		Project Manager: Ted Telisak	
Design Manager: N/A			Site Geologist: Teri McMillan
Design Engineer: N/A		Site Engineer: N/A	
Personnel on site	Name	Affiliation	Reason for being on site
EA:	Teri McMillan	EA	Drilling Oversight
Subcontractors:	Robert Joiner Cody Clayton Derek Withoff	Vortex	Driller
Other:	Chris Villarreal Eric Pastor Chris Moore Tim Nickels Roberta McClure	EPA PBW PBW PBW PBW	Drilling Oversight Environmental Consultant Environmental Consultant Environmental Consultant Environmental Consultant

#### **Work Performed**

Pastor, Behling & Wheeler, LLC (PBW) is the environmental consultant that is conducting the remedial investigation field activities. EA is providing oversight of field activities on behalf of EPA.

EA oversaw PBW as they installed three monitoring wells MW-18, MW-14, and MW-12 using a Mobil B61-HDX hollow stem auger drill rig. Monitoring wells were advanced adjacent to their respective Geoprobe® boring locations. The augers outside diameter was approximately 7.5 inch and the inside diameter was 3.25 inches. Clean augers were used to advance each borehole.

Borings for MW-18 and MW-14 were advanced to a total depth of approximately 25 feet below ground surface (bgs) and monitoring wells were installed. The total depths of the monitoring wells were approximately 24 to 24.5 feet bgs. The monitoring well consisted of 15 feet of 0.010-inch machine slotted screen and approximately 11 to 11.5 feet of blank riser (with 2 feet above ground surface). A filter pack consisting of 12/20 silica sand was placed from the total depth of the borehole (25 feet bgs) to approximately 8 feet bgs, followed by bentonite hole plug (hydrated) to 3 feet bgs. Cement then was placed from 3 feet bgs to the surface and an above ground shroud was placed over the riser, for an above ground completion.

It was noted that they installed something less than the minimum of 2 feet of filter pack above the well screens in wells MW-18 and MW-14. This was corrected for the next well location.

The boring for Well MW-12 was advanced to a total depth of 26 feet bgs and a monitoring well set at 25 feet bgs. The monitoring well consisted of 15 feet of 0.010-inch machine slotted screen approximately 12 feet of blank riser (with 2 feet above ground surface). A filter pack consisting of 12/20 silica sand was placed from the total depth of the borehole (26 feet bgs) to 8 feet bgs, followed by bentonite hole plug (hydrated) to 3 feet bgs. Cement then was placed from 3 feet bgs to the surface and an above ground shroud was placed over the riser, for an above ground completion.

During the advancement of borehole MW-12 the drill rig had a hydraulic leak. The rig was shut down for repairs. Plastic was placed beneath the rig where the leak occurred and hydraulic oil was cleaned up using adsorbent pads.

## **Anticipated Activities for the Following Day**

## DAILY FIELD ACTIVITIES SUMMARY REPORT

PBW and driller will continue to install monitoring wells. No oversight will be provided

## Report prepared by (name and date)

Teri McMillan 5/25/11

DAILY FIELD ACTIVITIES SUMMARY REPORT			
PROJECT NAME: R&H Oil/Tropicana Energy Site, San Antonio, Texas			
Date: 06/06/11	Shift Beginning: 10:45 hours		Shift Ending: 17:00 hours
RAC II Contract N	RAC II Contract No.: EP-W-06-004		Task Order No.: 0074
EPA Region 6 TOM: Chris Villarreal		Project Manager: Ted Telisak	
Design Manager: N/A		Site Scientist: Duane Thomas	
Design Engineer: N/A			Site Engineer: N/A
Personnel on site	Name	Affiliation	Reason for being on site
EA:	Duane Thomas	EA	Ground Water Investigation Oversight
Subcontractors:	N/A		
Other:	Tim Nickels John Brayton	PBW PBW	Environmental Consultant

#### **Work Performed**

Pastor, Behling & Wheeler, LLC (PBW) is the environmental consultant that is conducting the remedial investigation field activities. EA is providing oversight of field activities on behalf of EPA.

EA oversaw PBW as they resumed their groundwater sampling investigation, which had begun on Friday afternoon with MW-16 through MW-20 . PBW began the day by collecting LNAPL samples from 2 predetermined wells. One in the northern investigative unit (R&H Oil site) and one to the south. The LNAPL sample was collected via Geopump 2 peristaltic pump. LNAPL sampling began at MW-6. PBW was not able to collect sufficient LNAPL volume to submit for analysis. PBW (Tim Nickles) planned on replacing this sample, if possible, with another LNAPL impacted well in the southern unit. The impacted well in the northern unit that was sampled was NMW-3. PBW was able to obtain an LNAPL sample there with no issues. PBW chose to replace the MW-6 LNAPL sample with impacted well MW-5. NMW-5, initially planned for LNAPL sampling, was not used because it was not sufficiently impacted. MW-5 is in the southern investigative unit (Tropicana Energy site). PBW was able to sample sufficient LNAPL volume from this well. PBW submitted the LNAPL samples to be analyzed for TPH, VOCs, and physical properties.

After the LNAPL sampling was completed, PBW began preparations for the groundwater sampling. The method used for groundwater sampling was low flow micro purge via peristaltic pump. Water quality for stabilization was measured using a Horiba water quality meter. The water quality meter was calibrated prior to use. Turbidity was measured with a HACH turbidity meter. Water level and potential drawdown were measured using a KECK water level indicator. Ferrous iron was measured using a portable HACH DR 820 colorimeter. Monitoring wells sampled on this day were MW-15, MW-13 and MW-12. Samples were submitted for VOCs, SVOCs, metals and TPH.

PBW's SOP No. 9, page 2, paragraph F states that a plastic apron may be placed around a well before sampling. No such aprons were placed.

## **Anticipated Activities for the Following Day**

PBW will continue low flow sampling of on-site monitoring wells. EA will provide oversight.

## Report prepared by (name and date)

Duane Thomas 06/06/11

DAILY FIELD ACTIVITIES SUMMARY REPORT			
PROJECT NAME: R&H Oil/Tropicana Energy Site, San Antonio, Texas			
Date: 06/07/11	Shift Beginning: 07:25 hours		Shift Ending: 15:50 hours
RAC II Contract No	RAC II Contract No.: EP-W-06-004		Task Order No.: 0074
EPA Region 6 TOM: Chris Villarreal		Project Manager: Ted Telisak	
Design Manager: N/A		Site Scientist: Duane Thomas	
Design Engineer: N/A		Site Engineer: N/A	
Personnel on site	Name	Affiliation	Reason for being on site
EA:	Duane Thomas	EA	Ground Water Investigation Oversight
Subcontractors:	N/A		
Other:	John Brayton	PBW	Environmental Consultant

## **Work Performed**

Pastor, Behling & Wheeler, LLC (PBW) is the environmental consultant that is conducting the remedial investigation field activities. EA is providing oversight of field activities on behalf of EPA.

EA oversaw PBW as they continued their groundwater sampling investigation, beginning today with the low flow sampling at MW-14. Water quality for stabilization was measured using a Horiba water quality meter. The turbidity reading from the Horiba water quality meter was cross checked using a portable HACH turbidity meter. The water quality meter was calibrated prior to use. Water level and potential drawdown were measured using a KECK water level indicator. Ferrous iron was measured using a portable HACH DR 820 colorimeter.

PBW said that all onsite wells were gauged after the well development was completed on 06/03/11.

Monitoring wells sampled on this day were MW-14, MW-4, MW-1, MW-2, MW-6, MW-5 and MW-3. Monitoring well that were sampled and known to contain LNAPL were MW-6, MW-5 and MW-3. NMW-5 and NMW-4 were not sampled, but were gauged on 06/03/11. According to PBW, both of these wells were assumed to be impacted with LNAPL, therefore did not make the sample list. Samples were submitted for VOC's, SVOC's, metals and TPH.

PBW's SOP No. 9, page 2, paragraph F states that a plastic apron may be placed around a well before sampling. No such aprons were placed.

## **Anticipated Activities for the Following Day**

None. PBW has completed the groundwater investigation activities for this deployment.

#### Report prepared by (name and date)

Duane Thomas 06/07/11

EA Project No.: 14342.74 June 2011

EA Engineering, Science, and Technology, Inc.

## **ATTACHMENT 2**

## FIELD LOGBOOK

03,11 R&HOIL en Milhelan 330 or - sile > signed EA-HIS Plan. Christ Terionsla They are setting up on MW-18 houng geophoberg = 1335cleardel & raso - Collecting Sample from O-.5' Presend Sodium broowlate - Samping Conoller begrobing-uping actate 0-5'- Took next sample at ~ 4.5'- Based on factory 5-10'- - took PID every & mw-20- DTW encountered ~25'-went to 30' to see it. 10-1531 WC - 17' 5-20- can see oil staining 2012 as about - Definite HC ode Covered acetate scenes to stramewarm aig two us before sampled.

5/23/11 R&H OIL PID reading - L20204 Maternal Placedin Daggie thin crumbled & let to sit antable. Then PID meas taken DID measurements recorded on log forms. High meas fut seid at 5 5 dualed interest at V21-20 1415-MW-18 Geoprobe complete They put hale plug on barehale hydrated. They will come back and drill adjacent to set well 420 - Setting up on MW-14. They plan to geoprobe all Coations & them go back and Set wells. 1425 cleaning location at MW-14 for 0-.5' sample. 1424-Sottingup-PID for headopace of dullars. 1430 - commenced dulling/Geoprober 0-5' a cetate out - Pat Clay 5-10 force pand at 10 light gray -

5/23/11 REHON MW-43-5 Collected 2nd sample 14-4,5 methand gres. / 20 dum bisulate Diplicate Sample Collected erracore + sample kit 1442 10-15'- clay- 1 ght gray Caliche strong HC Eder-Staining possible - they are calling 05- oil shan from 15.0012/8- Some discoloration present - No Sheen - they are being consulating. 20-25'- Unore moist at a 20'-softer gravel at ~ 3.5'-1300-50-learner heliopen to See if water comes in Scheming head space. PID meadalements noted on dulling Cog Collected Prakhot PID for Lale @ 29, samples sangly 3eg for TPH Tx method, 8560 (UDCs) SUOCS & Metals RCRAS Samples once in Coopenindan

5/23/11 R\$HON 5/23/11 22 RAHOU mw-12 moved - b/c of booking 10-15'- Gravel at 14-15' Will tooke Gestech Sample otherise clay-w/ more sand 15-20' - Graine continued w/ from this Cocation 0:5' 1520- Collect Sgallon bucket for dene sand, to 18'-Gestech - 0-21 bgs us as wet from 18 - feet - where more deep as they went ph SC. Checked Plan - sample 1530- Started Gelproling MW-B 15:38- Sample madate sleeve States 0-Sto 4' logis. Showed this to chus Solled w/ Tap on outher and This is a deviation from 1-2' sample for vapor vole plans Mr influcion vapor transport 1611-20-25 sily clay wet package JEE model input Saturated at 20-21 essemanos. 1543- collecting 0-.5' Sample 7427ppm - bighest sid @ Privato probling in a location 20' 1620/21 727 ppm taking togacent to Vapor transport (Transmit Vadeal Dample @ 12 Sample at MW-12 0-5'. - Clay - dark gray - clayers and 1.030- Dace bag hale plug over bacie hale MW-12' mound 40 3-67 S-10! Clay - lighter gray TO next bocation Mu 30- at NMW-1 - Uisible more sand rear 10 - coliche. Surjace Oal sturing adjacent to this waster cal carb. - Slight oder HC 1552 - Ollected Dampie from \$-5 for Lab analyses ( 600 NOHC oder J. Millen took situe J. Nahullan

5/23/11 R\$HON 5/23/11 R&H OU 1635- Started geoprobung-1-Um Work to John - 104 Dulled out 1st S' Tabing PID measurements testan atmementadorna 019 Nood to get 0.5' Sample 20 14 -16 \$ 00 ndmas remains vigetation is -000-1040-1109 ppm-Stone - Then collected agd 41 to esquad prida [ Dample wind excore sumples Ill cuttings in drum/bucket. Same Preservatives as prevaud 730-cleanena up oute 730-offsito discussed 0-5' fill material w/ Black clay ~ 4-5' bas. 1645- Taloung Dample from 4 bgs tothe from cone-terra cone. 5-101-Clay- 5-5.4- grave/sand (Black) grading to lighter gray at 10 10-15- NAPL-OIL staining in Dample from 10-to 414 Scan Sandy Clay- leght gray Sand internals nino 1 15" Hule 15-20' Bottom of 20' - wet - WARL Sandy Clay - NAPL- present ( Commonwell ) throughout - on I stains Clay Sandy Clay water

S/24/11 R&HOD 5/24/11 R& Holl 815 arrived at Site 8:47-0-5'- full & layersand Chris Villarial arrived then black clay - Fat clay golleding sample ~ 4 as well. PWB staff. Hore Ton Wickels from MW-16 Chris Moore 5410'- Clay-gray Roberta McClive 10 30' - sandy clay -Mortex bas Geopuble 35MW-14 setting up on light gray Hc Goder 340 took 0. -0.5' Dample 900 TCEQ am-sde Removed Vegetation is shown them - took sample voxs Danu Sotal Sattman Marilyn Cona Terra core - 3 TOH, Metals They are covering up Samples w/ acetall to paul to SUOCs. 8:41: Moving gooprobe Erg in privent volathization 15 201 - light gray Cl Dace. TALED TOM WIPWB Sandyclay Moemosture they are only doing geoproby wet at ~ 18' gravel at base Clayer sand of ~ 17.5-18.2 complete to set wells. Channy out aide of Geograb Rods - w/ Atronso \*43 Began geopialmez & Worke Ring -HC oda Thong-Dee Vortex de cons Geoprobe discaland walk oil insde of Rod 4 ends aboutation J. McMillan J. McMullan

5/24/11 8/ # H OU 5/04/11 RX4 QU Adding another bag Bentoniu 20-25- Saturated + See hole plug of 2' bgo Product , took picture. gravel - then clay samples 9 25 Settera up on MW-13 9:34- Remound upper soil taken Product on out side atom care + veg to obtain the Put in plate baggies 0-0.3' sample - as they used à proje to collect at have done at previous 2 influesto crumble Locations - Samples Sample in loag. - Same as placed on the in cooler between PHD Calibrated 942 Mr Paster arrived ensitudade dag OO) at the ate. Eric Poster Same w/ air morter PID 0:591 - Black - Stauned placed at Geopholic Product - wet - 341. 40 S 15 Taking PID measurements Silly Clay-Reading pur ten on 950 whiled sample from borung log. 3-4' for lab PID medoursmonds 524.5 Collecting deplicate prinder - HHG to tolery Decemberg mades Rode Darnet for lab. 5-10' - black saturated 22- Hole plug Bentonle (Lagrania) w/01/-HC?-7 down bouhale -used 0-15 - 13ht gray clay
Sily chay 5'p pe to make sure of goedin 1- Solb bag Then hydratedw / water 3 Millan

5/24/11 R & N O Q 5/24/11 R \* H ON Measured water and in collecting Dunfoce Damples 14-MW78-000 A bgo 0-0.5' - Echaped Duface collected Etemps 15-201- Clay-sandy day 20-25'- NAPL-011-brown - Decommence sudgede of Clay-SHENCLON REdo as well as maide 600 m mundergraved ctay - 12.5 bys 0-5'- clay-fat clay gray grave 1/4" or less -046 collecting sample for Chacked to say there (al 8-3' closer to 3 elahord in vetou tow Displicate collected. Lep solow of 5-10'- Clay gray - light 1015 PID measurements lucy aft. s 12-15-clay-more Dond - undersely 9.8 ppm - 454 bgs. thes 15-20' Sed below Moram black wask oil PuB reeping log of headopace resouraments by dillers Geoprobers a 7822DT Columbia Highest PID was at 958.9 0 12.86go. 15-20' mottled grant yellowen Collacted Damose for Call brown (pale yallow) 20-25 Sandy day - 1 broad outhmark Agraniand gomburary Sand inducido Casa Vhan. 5" Wood for som taking PID Damples knuis -1110. They are going 5' deepen 1035-Set, up an bimw-2

5/24/11 R\$HOL 5/24/11 RAHOU 116 neasuring Head pace of Dample segmes Gestich Sample - Comuted to Duface - plus welled next chamawarment permission 10-15' bgs & 20' bgs Care in acodate as did 4 4 409 - OG & 2 tourset LICENSUS Collected Doil Sample 18-20 1385- Placena hole Plug in AND 13 TM MW 14. U HOL COL 25-30- more madre present 0-5' Fill surface. Sandy Clay- more ele Sand Black Clay- appears stained then (五二) avoils mant tracert gray clay CH-155 gravelly son clay - clay soft. Staining at a 5-10' - Sthy clay gray lighter graver'a 28'0 1130 Decenning Rods W/Deth-more sand/calcal w/deth 1308 Block on-site TM 1342 - collectura Sample from 0-3 for lab analysis 1305 measured DTW on 10-15'- sandy clay? more MMM-9 porepero ~18. Bandonile Hole plug placed sand lensos 15-20 - Sandy Clay - 4/ gravel bearled + Adaped on Character ) clay intervals Checkfor water in mw-B - NO worker will check again black oil stains : picture 316-Setting up on MWF15. 20-25'- wat - 221' right Scroping Ulg 2 dut. Comment C below growel 9 cover / sand to al - Then at bace Collected 5-0,5' bgs Soil gravel day. J. Miller I Millian

5/24/11 RAH Oil 5/24/11 R\$ H ord 1440 - Collecturg 2nd sample PID measurements taken 3-4 bgo-MsmsD Samples Hugh readings over 100 ppmv 20-25' = clay graveldy (耳) from 5.18 bys UBIH bas 779.4 PAMO MOLEN 1456 taking PID Measurements SOL sample collected measure with no usder yet lar lab. M NMW-3 4102 1710 Meadurements Above -100 FpmV 1415 Marelyn & Dance Starting at 5' bgo. left the Site CTCER "OG to meneruasem tasky 1422 Setting up on MMU-3 collected. Dinjace sample 1039 ppms taking 3rd 0-5' Fill modernal Sample for Laboratory at This cocation SAME analyses Fat clay 3.5-5 gray dark. as others. 5-10' Clay grading between Silty clay 8-10' Slight H Code 500 patting hole plug in boung now 15. 10-15 Headen Sandycky SID moong to MW-17 Canbon ca nodules 100 " section Setting up W/Sand at 10.5. gran mother Taking O-0.5' Sample al Bark gray - gasoline ada tor late. Possible staining at 15 Joseph State & SESI Sido' Sandy Clay - 1/5/45 ray then mothlers - 18'-20' Decommend marda appeared to be product of Geoproto Rod gasoline oda visible y wet Spossible NAPL hulkan J. Milhellan

5/04/1/ RAHOW D/04/11 KZM DU 1555 takena PID Measurements Before a cestale lines installed Œ are cleaning endo. PID high (Above 100 ppm) O-S' Fat clay & S' gray Dtauting at: 15 - 22 bys FILL mases above. Highest PID at Da with Now decomming bother 610 2P100 5 66mn. 5-10 Clay ~ 41 - than Dely NC collecting Danple Dample Clay On the Ca Cail nodules 1531 celledry Lob sample Islamalysis. from ~ 4' moleuse (600 Dutting Jable plug-Bentonite hydiated 10-15' Silly clay, staining 12 12' He odor in bounds mw-1+ Cal dal nodules, Minor sand longes (608 Setting up on mw 19 Collecting PID Damples HC stano 1614- Took Saylace Dample First removed Vog & top soil every 2 \$1. Placing hom in plaste baggies Labeled Then collected Cal 9-0.5 1616 started geopraling 30 Preurously done. 15-20 7 175 - HC stam ~ mw-19. 1" on length - Various smaller Decomming Rods Strens also obsavert. 0-5' Clayra 5 Fel alove duer than other barehales Thren operated. 00.25-grave -21- then 510 - Clay-mothed light Edule gray - 9'- Then went gray clair w Cacable noteils JARNAGEIG-06 - LOKOW 10-15" light clay adobover ca care nodules was obsured as well a I mcMillan J. mahella

5/24/11 RANOIL 5/84/11 RAHON Spoon-0-2'sample. I leade colleged and Lali Set upon MMW 5- getting 17030-0.5' sample for Col Dample from ~3-4'bgs. 15 20' Sandylday a sand lenes CT0 Darapid Sunface than took water sand lenous HC aday Collecting samples for PID as Samples A5 didat previous location (重量) Robart Joiner Duller before : every 212 in baggies Cody Clayton Heper Coumbling sample in baggie Linere on s/23/7/ Helpe Grand/clay cham 2/8 20 (<del>11</del>) Show observed poodelly CEL) - Dullers on site gray discoloration - water present Tuesding for Oortex. 20:05 - Wot - clanw/ grayer Chris & Eric Factor aredying -23 bgs- then clay silty day to find mws. solephigin TM LEC made not operating TAleing PID readings PID measurement high 7100 ppm Properly -1715 taking and Cal sample Nom 16 - 30' 16" mterval Nghest Ploat910.S. 0-5'- FIL+ Clay CH - 18'4-5' Taking sample for Cal 5-10'- Clay - silly clay at 15-16 6go, They are collecting soil bore bole WM-19. SAMPLES for 710 meas. every D' bap - as prevoudy 1655: getting Gentech: Brown done in other borings Slews - adjouent to 10-15' Clay w/ Ca Cach noduces. MW-20 liber spert J. Millelan 2 Millullan

5/24/11 RAH Dullery 5/04/11 R&HOU light gray to 17' bgo. Sample Bullentled To Then Harps more fam w/ Lab as collected as gray mostlers in/ more sand Eretrous Camples vere Minor Starrang possible All IDW stored in drums. 5-20' minor gravel at 17.5~ Custings placed on Sgal bucket then handpoiled Decenning Rodo as Huy to 55gal drum in tabe thank out. IDW starge and. Decorring bruses - w/ All IDW- water (Ram decon) (حلک KI conox I then water placed in 55 gal drumo Dense Ardu In IDW storage area 20-25 gravel and Sand 624.5 Deconning knives used interval - most sand that to cut samples for PID\$ I have seen in any borahde scrape surface of cone Wet - 24.5 Clayes present US/ Alcomox-DI Runaa A DBurg Bendonte Hole plug. 3 andry Thomas done blueach hale. 1748 - Setting Gep on NMW-4 alahala of Staining at Aut 20' PID Screening samples with in borm area where Release of 28000 gal gasdine Highest PID 20' Y07.0 Occurred. ( Company and 24'-172.3, 1755 Removed Wegetstern & ( Patternana) Calledong Dample at 19-20 lgs Deupace sol 20/ shoul They lended is in than collected 0'-0.5 Estimated sone but high measurement J. M. Pullar Soil sample for Lab J. M. Millan

5/24/11 D. M. M. Mellan 5/24/11 RAHOW Collected the Dame as 20-25' clay w/ minor Others Damples & Low gravel gravel layer from Dame anolysis. D.S.3' then more gravel, with clay 24 25 1757 - Began gabprobung 1820 Hold plug in bouhole Ni nestanti · 0 - 5 ' - FII - ~ 4' - Them CH Clay Hole plus hydrated. Measuring Hadopace w To south to 2ray PIO PID Presouvements Collecting Soil Sample for above 100 ppm - 8' logo. PID measurement as done before reging some technicipe 10' back down 219 then higher Principly described. 14' 1046 ppmv - highest 1803 collected soil sample themenuseours. for Lab (and sample) from 1825 collected Dal cample 44' bgs. using method from 13-14' bgotor lab previously described boat - ciayland 5-10'- Usible oil Staining protocolfor sampling as Low +4, 40 10 noted below. 1835 JLONE Clay gray 10-15' Eloy Wolfled wy dark gray 12 - Light gray w/ ca can modules to to possible Stauring 15-2015, thy Bay apalous oft near 201 Stayning Michillan

5/25/11 R # HOD 5/25/11 RAHOLL drum. 8:00 annued at site 950 Talked to tim W/ Duller and PWR on-sile PBW all wells will Signed 2A HES Flan be screened 10 slot = 12/20 as I did for past 2 Silica samoli agus Some wells may be growned 815 Chus Ullarreal to 30'- They need to stell chock some boucholes allo mo brunco 830 HSA Rig - Blel-HDX 00- F.S Mobile Drill Land of the land o that were light open to See if water came in 士口 3/4 overlight. They well no qui portese extra up on deade To based on this. MW-18 = to Unotale Checking breathing some well. Let up adjacent Manager ( to Geoprobe bound 906 Peached TD, of 25° Placing bood plug und sugar to mottod Enodaing botham blug Chris tailled to Tum w/ PWB- He planson from bottom of augalo: Placed casing in aliquo Screening lack, well Juan 10-25 down hale Screen 10 slot sand using tag une to measure in around space 12/20 Silica Adding Sand. han Drill asky as are Pulling out augens slowery bung placed in 55 gal A Millellan

Slos/11 REHOW 5/25/11 RANOQ 945 - Discussed have plug 400 Alaum on PA 40 Dentace or 3, of Ch. - Not Deustrened Durjoce 10/ PBW They are doing this motered So Hose pund 40 3 shallow or more than I minute Will monder closely. Top of found 8' bas Thus is appropriate Addubb bentonile Hole 947 Mixing cement. Plug-Phydroting 3/8 Asked Question regarding top of Soundanite at \$ 3' bas Then concerte for Sandpack for MW-13 Asked of they thought it sãd 3-surface send stangerggs con Strick up will complations gross contamination fresent to approx 7' bgs wal is i foot above Surface SOTO 204' bgo tim is trunking should Brought out PBW's Hos 950 putting cement down hole & Protalling Should plan - to look over 000 Moving to rext-location Thur specs for Cevel C MW-W Just states the I ppm 1010-Talked to Trm -Sustained They have asked of ho wasgoing Moder Sot for 50 Alarm to have them diele back -will check "closuley to through hale Plag -See Lat I ppm - and then See If guitarned for Weses He said No adjust to I S. W. Millar -Uni Millar

5/25/11 R\$HOQ 5/25/11 R \$ H OR Aig is Set up to drull - Abbung sand fill parts driedly over the Annulus opace - Annulus Turn dieded them to Stayospen - Well of y 24.5' bgs. 1020 Started dulling MW-14. SAND at 8' bgo (Taranama) All outtings gouting in 55 gallon druting TOP of Derson is at 9.5' bgs ~1.5'of This aralso decorning Dand albur Screen! the dugers. 1109- BAD ADDUNG Brotonite (Limited) Tom with PBW is halo plug hydrating as go ? Bentake topol monitoring ou space WITH PID. Transmit D wadens, up augers 1040; pushed wood Plug dom bottom of hale will goderon dugers dram from Three Roles - Not Much worter on Will continue dulling with clean augus on Dud un coura 25 15' screen 10 stot Adding father pack 12/20 Mixing coment will Drive souls Bet Oshrand at mw-14 Monitoring brooking 130. Setting upon Mw-12 Geoprobe bouhale was Boro googs Never plugged u/ Bontonile 1100 Pulled augers out. Hole pleigging Bouldones D. Mchiller J. Withalla-

5/25/11 R\$H ore Slasin RANDO 1315 - Bedge on oute Discussed the duration Discussed with I'm of min of 2' sand pack about Sand pack of above to Her pack with chuis placed min d'alove He was fine with Slight duration Jordan. He was correct this on next wells. Dulling New Locahole 1350 Quellero repairing mg ~ adjacent to hale: that was hale plegged. (englamod butters) 1140 - Started drillera, MW-12 all Mws - 9 regardless Dulled to S' then are of NAPL present or not. No que samples will taking a gastech. Sample De Collected from W brass slewer unded 100 Bulling again at SS Started drilling again 150 began decon of 75° of augers took MW-12-0 ald more bondand gravel in this use of Ob a cutting a 20' 1201- leak on Rea hey are going to dulto heydraulec Cemos approx No to accomidate But plastic below rig tid llnd to mothed ni pull that be bestowed as that to cotch so will have to replace the 1442 - Dushing Plug Gram bottom Dull told out 1910-afternator mind milla < 1 M. Willen

5/25/11 R4HOU 5' 3 creen 10 slot 0' Blank cosina well at 25' bgs of adding Alter Sack 12/20 Silvea sand Plaung cound in Uts w/ tag une Then pulling agers up Slowly. Sand top of at SILO ADDEMA Bentonte Hole place hydrothing as they got of at 3! Talle - Didles Up on put well will only go S today 1620=

Sun Autorio, TX ROHO. 5/25/U R4HOU Dane Thomas Ourself 15' screen 10 slat 0645 Depart Housign 10' Blank cooma 1007 Arrive posite well at as bas adding Alter Back Wenther: Hot, mis fly surry, high near 9908. Winds loft from 12/20 Silva sand. Plaung and in lifts w/ tag line Then Paling agers up PLAN FOR THE DAY! Bean oversuplif of Slaudy. PRP contactor PBW > groundwater Sand top of at 8' bgs. investigation via low tow sampling SILO ADQUIA Bentonite 1000 PBW not onsite Hole place hydroting as they got of at 3' bgs 1045 BUDAS/10 PBW STAFF: Jim Nickles EA: Diage Thomas 100 Tim Nickles wasting on John Brayton lelle- Dilles Selling (field samples) to arrive onsite from the Up on put well will Oney go s' today before sumplish designs. 1128 Down Bray for (PBW) on sixe 1620 - OH - SITE 1:40 John Browson says PBW w:// a fempt to grad a NAPL sample great to low flow sampling 1148 Noo Lo MWE For CNAR rample - NAPR obtained using Geopump porstaltic PUMP

Sun Antonio, TX RYH O.-/ 04/06/11 San Antonio, TX, RXH O. 00/00/11 -05 = 20ml Ashal LNAR recovered colorimeter Lauping encled 206 Mod Lo ALW-3 FOR CNAR 438 m Begin set up on MW-13 \* Those set of on MW-B = sood LNAR recovery - MBW experiencing draw down, J.B. lavers 31-LNAR sample for NMW-3 complete 1238 Mob, Lo MW-5 for LNAPL SAMKETIME NW-13 1530 1535 Sampling complete \* Thoso: LNASL sampling 1540 Mos to MW-12 1558 End LNAPE Sumples 1550 Begin set up on new-12 - Good recovery for LINAPL 1300 Begin load upfor low flow scampling 195,3, tump on Thoro: Sampling of MW-to 325 Mod to MW-15 1650 Sample Time MW-12 A Water quality meter; Horiba Calibrated: 00/00/11 Kimpon = /330 draw down was measured KECK water level indicator 1840 Per Tim Nickles, MW-6 samples discardel. (NAPL SAMPLES) due 46 pour recovery NAPL samples came from NMW-3 and MW-5 430 Sample time MW-15 Tample Sweet: UgC'S metals, SUOC'S \* Ferrous From being Field lested HAKH DR&G

San Amorio, TX B. 440:1 Sun Haronis TX RXHO! 0945 Begin set up on MW-1 5/00 Deput SA Fors/te 0725 Arrive on sife 1020 SAMPLE TIME MU-1 WEATHER: Mostly surry, but and burned. \* Photo: Set up, on Mw. News second highes of 990F Winds 30 Mw-1 Sayply complete 2015 E 20 light from South 1035 Meb to MW-2 RAN FOR THE DAY: Contine oversight of 1036 Begin Set up on MW-2 PRP contractor Bluggoond water of Jump On Secretaria de la constantida del constantida de la constantida de la constantida del constantida de la constantida de la constantida del constantida de la constantida del con sumpling event \* Photo: sampling of MW-2 0735 Mob to MW-14 to begin day's - NMW5 develorasor/11 gaised offer developmen investigation. 0005/11 - field instruments calibrated Turbed: Ly being measured on Horiba water 5742 Kmp on quality meter and dooble checked with \* Thoto: sampling of MW-fl HACH fordidity meter 0830 SAMPLE TIME MW-KE (Pop faken) 1121 Sampling at MW-2 complete 2844 sampling Mw-14 complete 130-1220 Lunch Break 6245 Mos Lo MW-4 1224 Mob to MW-6 0855 Pump On 225 Begin set up an MW-6 (LWAR IMMENTED) 355 to 10/4 Netbal and newtoral unchanged well) (0.02") tom yesterday oce/oce/4. - MS/MSD taken here EA Stoff: Page Thomas PBW Shaff: John Brayfor B15 Sample Time MW-6 DTSO MW & SAMPLE TIME, 1348 Saude Complete 094/ MW-4 Sample completed. 1349 Mod to NW-5 (CNAPL) impacfed 0944 Moblo MW-1 mell

EA Project No.: 14342.74 June 2011

## ATTACHMENT 3 PHOTOGRAPHS



Photograph No. 1 Description: MW-18. Collecting surface samples.



Photograph No. 2

Description: MW-18. Geoprobing.



Photograph No. 3 Description: MW-18. Core 0-5'.



Photograph No. 4

Description: MW-18. Core 0-5' and 5-10'.



Photograph No. 5

Description: MW-18. Core staining 10-15'.



Photograph No. 6

Description: MW-18. Core with acetate liners to prevent volatilization.



Photograph No. 7 Description: MW-18. Labeling of core.



Photograph No. 8
Description: MW-14. Cleaning surface prior to sample collection.




Photograph No. 9

Description: MW-14. Geoprobing.



Photograph No. 10

Description: MW-14. Terra core sampling from 0-5'.



Photograph No. 11

Description: MW-14. PBW logging core.



Photograph No. 12

Description: MW-14. Gravel in 20-25' interval.



Photograph No. 13

Description: MW-14. Taking PID measurements.



Photograph No. 14

Description: MW-14. Hole plug bag placed over borehole. Borehole left open to gauge water level.



Photograph No. 15 Description: MW-12. Sample collection for geotechnical analysis.



Photograph No. 16

Description: MW-12. Geoprobing.



Photograph No. 17
Description: MW-12. Vapor intrusion, vapor transport package in 1-2' acetate liner.



Photograph No. 18

Description: MW-12. Geoprobing.



Photograph No. 19
Description: MW-12. Core covered with acetate liner to prevent volatilization.



Photograph No. 20

Description: MW-12. Gravel in 10-15' interval.



Photograph No. 21 Description: MW-12. Moisture from 15-18', wet from 18-20'.



Photograph No. 22

Description: MW-12. Taking PID readings.



Photograph No. 23
Description: MW-12. Borehole covered with hole plug.



Photograph No. 24

Description: NMW-1. Geoprobe setup.



Photograph No. 25 Description: MW-14.



Photograph No. 26 Description: MW-12.



Photograph No. 27 Description: NMW-1. Stake.



Photograph No. 28

Description: NMW-1. Surface staining.



Photograph No. 29
Description: NMW-1. Surface staining.



Photograph No. 30

Description: NMW-1. Setting up geoprobe and surface staining.



Photograph No. 31

Description: NMW-1. Surface cleared for sampling.



Photograph No. 32

Description: NMW-1. Surface sampling.



Photograph No. 33

Description: NMW-1. Surface sampling.



Photograph No. 34

Description: NMW-1. Oil staining on 10-15' core interval.




Photograph No. 35 Description: NMW-1. Oil staining on 10-15' core interval.




Photograph No. 36

Description: NMW-1. Staining on 15-20' core interval.




Photograph No. 37

Description: NMW-1. Staining on 15-20' core interval.




Photograph No. 38

Description: NMW-1. Staining on 15-20' core interval.



Photograph No. 39

Description: NMW-1. Staining in 20-25' core interval.



Photograph No. 40

Description: NMW-1. Gravel in 20-25' core interval.



Photograph No. 41 Description: MW-16. Stake.



Photograph No. 42

Description: MW-16. Surface sample.



Photograph No. 43

Description: MW-16. Setting up geoprobe.



Photograph No. 44

Description: MW-16. Acetate liner.



Photograph No. 45
Description: MW-16. Decontaminating the inside of geoprobe rods.



Photograph No. 46

Description: MW-16. Decontaminating the inside of geoprobe rods.



Photograph No. 47

Description: MW-16. Collecting soil samples for PID every 2'.



Photograph No. 48

Description: MW-16. Decontamination.



Photograph No. 49 Description: MW-16. Core.



Photograph No. 50

Description: MW-16. Core.



Photograph No. 51

Description: MW-16. Core, wet at 18'.



Photograph No. 52

Description: MW-16. Core, possible staining 20-25' interval.



Photograph No. 53
Description: MW-16. PID and LEL meters measuring the breathing zone.



Photograph No. 54

Description: MW-16. Terra core sampling.



Photograph No. 55
Description: MW-16. Plugging borehole.



Photograph No. 56

Description: Decontamination area.



Photograph No. 57 Description: MW-13. Stake.



Photograph No. 58

Description: MW-13. Surface sample.



Photograph No. 59

Description: MW-13. Geoprobing.



Photograph No. 60

Description: MW-13. Sample, black wet oil sludge 0-5'.



Photograph No. 61

Description: MW-13. Sample, black wet oil sludge 0-5'.



Photograph No. 62

Description: MW-13. Sample, black wet oil sludge 0-5'.



Photograph No. 63 Description: MW-13. Core.




Photograph No. 64

Description: MW-13. Sample collection from approximately 4' bgs.



Photograph No. 65

Description: MW-13. Preparation for geoprobing.



Photograph No. 66

Description: MW-13. Top of 5-10' core interval.



Photograph No. 67 Description: MW-13. Middle of 5-10' core interval.



Photograph No. 68

Description: MW-13. Middle of 5-10' core interval.



Photograph No. 69 Description: MW-13. Core.



Photograph No. 70 Description: MW-13. Core.



Photograph No. 71

Description: MW-13. Core.



Photograph No. 72

Description: MW-13. Water and possible oil.



Photograph No. 73

Description: MW-13. Measuring headspace with PID.



Photograph No. 74

Description: MW-13. Soil sample collection.



Photograph No. 75

Description: Decontaminating sampling knives.



Photograph No. 76

Description: NMW-2. Stake.



Photograph No. 77 Description: NMW-2. Clearing location for surface sampling.



Photograph No. 78

Description: NMW-2. Decontaminating geoprobe rods.



Photograph No. 79

Description: NMW-2. Setting up PID and LEL meters.



Photograph No. 80

Description: NMW-2. Core 0-5'.



Photograph No. 81 Description: NMW-2. Black mottling and black oil staining 0-5'.




Photograph No. 82 Description: NMW-2. Black mottling and black oil staining 0-5'.



Photograph No. 83 Description: NMW-2. Core.



Photograph No. 84 Description: NMW-2. Core.



Photograph No. 85

Description: NMW-2. Core, interval in front is 20-25'.



Photograph No. 86

Description: NMW-2. Core.



Photograph No. 87

Description: NMW-2. Plugging borehole.



Photograph No. 88

Description: MW-15. Stake.



Photograph No. 89

Description: MW-15. Core 0-5'.




Photograph No. 90

Description: MW-15. Black staining 15-20'.



Photograph No. 91 Description: MW-15. Core.




Photograph No. 92

Description: MW-15. Core, gravel 20-25'.



Photograph No. 93 Description: MW-15. Core.



Photograph No. 94 Description: NMW-3. Stake.



Photograph No. 95

Description: NMW-3. Geoprobe setup.



Photograph No. 96

Description: NMW-3. Core 0-5'.



Photograph No. 97

Description: NMW-3. Core 0-5'.



Photograph No. 98

Description: NMW-3. Core 0-5'.



Photograph No. 99 Description: NMW-3. Core 0-5'.




Photograph No. 100

Description: NMW-3. Core, taking samples for PID readings.



Photograph No. 101

Description: NMW-3. Core 5-10'.



Photograph No. 102

Description: NMW-3. Core, possible staining 10-15'.



Photograph No. 103 Description: NMW-3. Core, possible staining 10-15'.



Photograph No. 104 Description: NMW-3. Core, possible staining 10-15'.



Photograph No. 105

Description: NMW-3. Core 20-25' interval.



Photograph No. 106

Description: NMW-3. Soil sampling.



Photograph No. 107

Description: NMW-3. Soil sampling.



Photograph No. 108

Description: MW-15. Plugged.



Photograph No. 109 Description: MW-17. Stake.



Photograph No. 110 Description: MW-17. Stake.



Photograph No. 111

Description: MW-17. Setting up geoprobe.



Photograph No. 112

Description: MW-17. Surface soil sample.



Photograph No. 113

Description: MW-17. Geoprobing.



Photograph No. 114

Description: MW-17. Geoprobing.



Photograph No. 115
Description: MW-17

Description: MW-17. Geoprobing.




Photograph No. 116

Description: MW-17. Geoprobing.



Photograph No. 117

Description: MW-17. Core 0-5'.



Photograph No. 118

Description: MW-17. Core 0-5'.



Photograph No. 119 Description: MW-17. Core.



Photograph No. 120 Description: MW-17. Core.



Photograph No. 121

Description: MW-17. Hydrocarbon staining at 15-20' interval.



Photograph No. 122

Description: MW-17. Core.



Photograph No. 123

Description: MW-17. Core, gravel at 20-25' interval.



Photograph No. 124

Description: MW-17. Core, gravel at 20-25' interval.



Photograph No. 125

Description: MW-17. Plugging borehole.



Photograph No. 126

Description: MW-17. Plugging borehole.



Photograph No. 127 Description: MW-19. Stake.




Photograph No. 128

Description: MW-19. Surface soil sample.



Photograph No. 129

Description: MW-19. Geoprobing.



Photograph No. 130

Description: MW-19. Core, 0-5'.



Photograph No. 131

Description: MW-19. Core, 0-5'.



Photograph No. 132 Description: MW-19. Core.



Photograph No. 133

Description: MW-19. Sampling soil.



Photograph No. 134

Description: MW-19. Wet, possible sheen observed at 15-20' interval.



Photograph No. 135

Description: MW-19. Core, wet at 20-25' interval.



Photograph No. 136 Description: MW-19. Core.



Photograph No. 137 Description: MW-19. Core.



Photograph No. 138

Description: MW-19. Borehole plugged.



Photograph No. 139

Description: NMW-5. Stake.



Photograph No. 140

Description: NMW-5. Surface sample.



Photograph No. 141

Description: NMW-5. Core 0-5'.



Photograph No. 142

Description: NMW-5. Core.



Photograph No. 143 Description: NMW-5. Core.



Photograph No. 144

Description: Decontamination.



Photograph No. 145 Description: NMW-5. Core.



Photograph No. 146 Description: NMW-5. Core.



Photograph No. 147 Description: NMW-4. Stake.



Photograph No. 148

Description: NMW-4. Surface sampling.



Photograph No. 149

Description: NMW-4

Description: NMW-4. Geoprobing.



Photograph No. 150

Description: NMW-4. Geoprobing.



Photograph No. 151

Description: NMW-4. Geoprobing.



Photograph No. 152

Description: NMW-4. Geoprobing.



Photograph No. 153

Description: NMW-4. Table set up for looking at samples.



Photograph No. 154

Description: NMW-4. Core 0-5'.



Photograph No. 155

Description: NMW-4. Core 0-5'.



Photograph No. 156

Description: NMW-4. Staining on 5-10' core interval.



Photograph No. 157

Description: NMW-4. Staining on 5-10' core interval.



Photograph No. 158

Description: NMW-4. Core.



Photograph No. 159

Description: NMW-4. Core, hydrocarbon staining at 15-20' core interval.



Photograph No. 160

Description: NMW-4. Core.



Photograph No. 161 Description: NMW-4. Core.



Photograph No. 162 Description: NMW-4. Core.



Photograph No. 163

Description: NMW-4. Core, gravel at 20-25' interval.



Photograph No. 164

Description: NMW-4. Core, gravel at 20-25' interval.



Photograph No. 165

Description: NMW-4. Core, gravel at 20-25' interval.



Photograph No. 166

Description: NMW-4. Plugging borehole.



Photograph No. 167 Description: NMW-4. Core.



Photograph No. 168

Description: NMW-4. Sample collection.



Photograph No. 169

Description: MW-18. Hollow stem auger drilling.



Photograph No. 170

Description: MW-18. Drilling for monitor well installation.



Photograph No. 171

Description: MW-18. Installing well casing.



Photograph No. 172

Description: MW-18. Setting filter pack in well annulus.



Photograph No. 173

Description: MW-18. Well installation.



Photograph No. 174

Description: MW-18. Well installation.



Photograph No. 175

Description: MW-18. Setting filter pack.



Photograph No. 176

Description: MW-18. Removing auger.



Photograph No. 177

Description: MW-18. Setting filter pack.



Photograph No. 178

Description: MW-18. Setting bentonite chips for the seal.



Photograph No. 179

Description: MW-18. Mixing cement for well pad.



Photograph No. 180

Description: MW-18. Well installation.



Photograph No. 181

Description: MW-18. Completing the well.



Photograph No. 182

Description: MW-18. Well stick-up.



Photograph No. 183
Description: MW-18. Well stick-up.



Photograph No. 184

Description: MW-14. Drilling.



Photograph No. 185

Description: MW-14. Well installation.



Photograph No. 186

Description: MW-14. Well installation.



Photograph No. 187

Description: MW-14. Well installation.



Photograph No. 188

Description: MW-14. Well installation.



Photograph No. 189

Description: MW-14. Well installation.



Photograph No. 190

Description: MW-14. Well installation.



Photograph No. 191

Description: MW-14. Well installation.



Photograph No. 192

Description: MW-12. Drilling.



Photograph No. 193

Description: MW-12. Plugging geoprobe borehole.



Photograph No. 194

Description: MW-12. Drilling.



Photograph No. 195 Description: MW-12. Drilling.



Photograph No. 196

Description: Decontaminating augers.



Photograph No. 197

Description: Decontaminating augers.



Photograph No. 198

Description: MW-12. Drilling.



Photograph No. 199

Description: MW-12. Hydraulic leak on drilling rig.



Photograph No. 200

Description: MW-12. Drilling.



Photograph No. 201

Description: MW-12. Drilling.



Photograph No. 202

Description: MW-12. Cuttings.



Photograph No. 203 Description: MW-12. Cuttings.



Photograph No. 204

Description: MW-12. Drilling.



Photograph No. 205

Description: MW-12. Cuttings.



Photograph No. 206

Description: MW-12. Adding filter pack.



Photograph No. 207

Description: MW-12. Adding filter pack.



Photograph No. 208

Description: MW-6. PBW performing LNAPL sampling.



Photograph No. 209 Description: MW-13. Low-flow sampling set up.



Photograph No. 210
Description: MW-12. PBW sampling.

June 2011



Photograph No. 211 Description: MW-1. PBW sampling.



Photograph No.  $\overline{212}$ 

Description: MW-2. PBW sampling.



Photograph No. 213 Description: MW-5. PBW sampling set up.



Photograph No. 214 Description: MW-3. PBW sampling.

EA Project No.: 14342.74 June 2011

EA Engineering, Science, and Technology, Inc.

## **ATTACHMENT 4**

## WELL LOCATION MAP

from PRP Field Sampling Plan by Pastor, Behling, and Wheeler

